

Key to Photographs

N. Y.  
56 - Newp  
3

Jean Hasbrouck House (1712)  
New Paltz, New York  
Ulster

- 3) Exterior general view from south and west. July 25, 1940.  
Photos by Stanley P. Nixon.
- 4) Exterior general view of rear and end, from west and north.
- 5) Exterior general view of rear from north.
- 6) Exterior east end and front, from east.
- 7) Ext. detail of front entrance porch, from south.
- 8) Exterior detail, wood barred window to cellar, south west end.
- 9) Interior detail, fireplace end and cupboard, east room,  
first floor.
- 10) Interior east side of north room, first floor.
- 11) Interior detail of door and cupboard, west side of north room,  
first floor.
- 12) Interior corner cupboard, and location fireplace, north room,  
first floor.
- 13) Interior construction detail of wall between hall and room,  
first floor.
- 14) Interior south wall of kitchen, present paneling, under  
old hood.
- 15) Interior basement, "ladder supports" for shelves, front cellar.

N. Y.  
56 - Newp  
3

- 16) Interior "turn table", front cellar shelves.
- 17) Interior doorway between front and rear cellars, showing hardware.
- 18) Interior detail, hearth support under kitchen, west corner of cellar.
- 19) Interior attic framing, looking toward side of kitchen chimney, from north east.
- 20) Interior view in attic, showing brick hood and flue, from old kitchen.
- 21) Fragments, dutch door, and blind from attic, showing hinges.
- 22) Fragments inside blind, piece of paneling, corner cupboard cornices.